



MakMax Carpark Repairs, Reskin & Maintenance

Extend The Life Of Your Carpark

To maximise the lifespan and maintain warranties of your tensile membrane structure, a routine inspection and maintenance program will identify standard wear and tear.

MAKMAX AUSTRALIA POST PROJECT SERVICES

- » Routine Engineering Inspections & Reports
- » Warranty Inspections
- » Programmed Cleaning & Maintenance
- » Engineering Repairs
- » CAPEX Works - Re-skins or Replacements

Design. Engineer. Fabricate. Install.



MakMax Post-Project Services



ROUTINE ENGINEERING INSPECTIONS & REPORTS

MakMax recommends engineering inspections at least every 3 years, or after any severe weather event.



WARRANTY INSPECTIONS

Most manufacturers stipulate regular warranty maintenance inspections by an engineer or qualified person.



PROGRAMMED CLEANING & MAINTENANCE

Over time, various environmental impacts can cause contaminant build up and discolouration. MakMax can arrange cleaning of your membrane canopy to prolong lifespan and maintain warranty.



ENGINEERING REPAIRS

With appropriate maintenance your structure is designed to last for many years. Should any structural element begin to show damage, it is important to have those sections replaced or repaired.



CAPEX WORKS - RE-SKINS OR REPLACEMENTS

MakMax can inspect and propose a solution to either repair or replace the membrane. In most cases the supporting steel frame can be kept in-situ.

TYPES OF DAMAGE



STORM DAMAGE



IMPACT




VANDALISM



DUST/POLLUTION



FIRE




EXPECTED LIFESPAN



Redbank Plains - Before



Redbank Plains - After



Lake Haven Shopping Village - Before



Lake Haven Shopping Village - After

Design. Engineer. Fabricate. Install.

MakMax Australia

1300 625 629 | info@makmax.com.au | www.makmax.com.au



SCI QUAL INTERNATIONAL

WWW.JAS-ANZ.ORG/REGISTER

March 2021